MATERIAL SAFETY DATA SHEET

Section 1 Chemical product and company identification

PRODUCT NAME: Zirconium Oxide

ISSUED DATE: 07/09/2008

SUPPLIER: xuan cheng jing rui New Material CO.Ltd.

Qilin road,xuan zhou economic development zone,xuan cheng city,anhui province,China

Tel: +865632062263 Fax: +86571-81131920

E-mail: jingruinm@163.com

EMERGENCY CALL: +86-15856339196

Section 2 Composition

Component	Formula	Molecular Weight	CAS Number	% by Weight
Zirconium Oxide	ZrO2	123.2188	1314-23-4	85-100

Physical/Chemical Properties Appearance: White to offwhite: granules Odor: Odorless Solubility in H2O: Insoluble S.G.(g/cc): 6 Melting Point: >2715° C(4919° F) % Volatile: 0 pH: N/A

Section 3 Hazard Identification

Target Organs: Skin, eyes, and lungs

Caution: Handling or machining of these products may produce respirable dust particles. Dust may irritate eyes, skin and respiratory tract.

Inhalation: Dust may cause irritation or soreness of throat and nose.

Eye Contact: Dust may cause temporary irritation or inflammation.

Skin Contact: May cause temporary dryness, irritation or rash.

Ingestion: Ingestion is unlikely. May cause gastrointestinal disturbances. Never induce vomiting without the advise of a physician.

Medical Conditions Aggravated by Exposure: Respiratory effects may be aggravated by smoking. Pre-exiting respiratory problems may be aggravated by dust.

Section 4 Exposure Controls

Engineering Controls: Use dust suppression. Local exhaust ventilation, point of generation dust collection, and/or down-draft work stations to minimize airborne, dust generation is recommended when machining product.

Respiratory Protection: Use appropriate protection pursuant to OSHA 29CFR 1910.134 and 29CFR 1926.103. The following information is provided as a guide and reflects industry recommendations for control of dust:

PPE < 1.0 /cc: No specific recommendation, use personal protective equipment based on local

conditions.

PPE 1.0 f/cc to 5.0 f/cc: Half-face, air purifying respirator equipped with a high efficiency particulate air (HEPA) filter cartridge.

PPE 5.0 to 25 f/cc: Full-face, air purifying respirator equipped with a high-efficiency particulate air (HEPA) filter cartridge.

PPE > 25 f/cc: Full-face, positive pressure, supplied air respirator

PPE Other: Work clothes should be washed separately and the washing machine rinsed following use. If possible, do not take work clothes home following

machining or removal activities that produce significant amounts of dust.

Skin Protection: Wear gloves and full body clothing to prevent skin irritation. Store work clothes and street clothes separately.

Eye Protection: Wear safety glasses or goggles. Do not wear contact lenses without goggles. Do not get into eyes. Have eye wash available.

Note: These products are generally not hazardous during normal use. These guidelines are provided for special circumstances involved in machining, use and / or after service removals.

Section 5 First Aid

Inhalation: Remove to fresh air. Rinse mouth to clear throat and expel liquid. Blow nose to evacuate dust. Consult a physician if irritation persists.

Eye Contact: Do not rub eyes. Keep hands or contaminated body parts away from eyes. Remove contact lenses. Flush with water. If irritation persists, consult a physician.

Skin Contact: Wash with soap and water. For dryness, a skin cream may be helpful. Do not apply anything to a rash. Consult a physician if irritation persists.

Ingestion: Do not induce vomiting without advice of a physician. Seek medical attention.

Section 6 Fire Fighting Measures: Materials are not combustible.

Section 7 Accidental Release Measures

Spill Procedures: Clean up procedures should minimize formation of airborne dusts. Remove dust by vacuuming using HEPA filtration where possible. Liquid and moist products (groups 2 & 3) should be cleaned up with sponge, mop or cloth.Release into Air: Prevent release of airborne particulates where possible. Not a regulated hazardous substance. Release into Water: Release into water is not appropriate. Not a regulated hazardous substance. Landfill dusts and debris consistent with local regulations.

Section 8 Handling & Storage:

Storage: These materials are stable and may be stored indefinitely. Physical abrasion may produce small amounts of respirable dusts. Liquid and moist products (groups 2 & 3) should be stored in a sealed container.

Normal Use: Materials are stable under normal use and are not expected to produce significant hazardous by-products or emissions.

Machining and Cutting: These materials may produce respirable and nuisance dusts when machined or cut.

High Temperature Conditions: Service significantly above the product design temperature may increase friability and the possibility of generating airborne

fibers or particulates. While not considered problematic during use, airborne fibers may complicate removal activities. It is recommended that product use be carefully matched to design parameters.

After Service: Product removal must consider the possibility of usage above design temperatures.

Section 9 Stability & Reactivity

Stability: Materials are stable.

Chemical Incompatibilities: Powerful oxidizers; fluorine, chlorine trifluoride, manganese trioxide, oxygen difluoride, etc.

Hazardous Decomposition Products: None.

Section 10 Disposal Information

Disposal: Consult with local, state and federal regulations. In most cases these materials may be land filled safely.

Hazardous Waste Classification: Not listed as a RCRA Hazardous Waste (40 CFR 261.31). Not listed under SARA, CERCLA, or the Clean Air Act.

Empty Containers: Empty containers may contain product dust or residue. Do not re-use. Disposal regulations vary. Consult with all applicable regulations prior to disposal.

Section 11 Transportation Information: Not regulated hazardous substances, no specific regulations apply

Section 12 Toxicology & Ecological Information

Toxicological Information: No Information available

Epidemiology: No Information Available

Distribution: Zirconia and silica are naturally occurring and are widely distributed in igneous rock. Deposits in sedimentary rock may be found.

Chemical Fate Information: The relative inertness of this material indicate that it may be highly persistent in the environment. No information regarding any negative effects of this persistence has been noted.

Section 13 Regulatory Information

Regulated Constituent: Zirconium Oxide

CENTER to Know: listed

listed N.J. CENTER to Know: none

New Jersey CENTER to Know Note: The listed substance is found on the New Jersey Hazardous substance list and is subject to reporting under SARA and the New Jersey Worker and Community CENTER to Know Act.

Mass. CENTER to Know Note: Items on the Massachusetts List of Hazardous Substances require specific hazard labeling in the workplace.

Proposition 65 chemicals which are "known to cause cancer" by the state. Proposition 65 lists all substances classified by the IARC as a Category 1, 2A or 2B

carcinogen.

human carcinogen. There is sufficient evidence of carcinogenicity in animals, but limited evidence in humans. The recommended TLV for respirable cristobalite

is 0.05 mg/m³. Appropriate ventilation and respiratory protection should be provided in compliance with OSHA standards. Strict adherence to recommended safework practices is advised.

SARA Section 313 Supplier Notification: This product does not contain toxic chemicals subject to the reporting requirements of the Superfund Amendments and Reauthorization Act of 1986 Section 313 (40 CFR 372).

TSCA Statement: All ingredients are listed in the TSCA Inventory.

Section 14 Other: The information contained herein is based on data considered to be accurate as of the preparation or revision date. It is provided in good faith and in compliance with state and federal regulations. No warranty or representation, express or implied is made as to the accuracy or completeness of this information.

Other national, state and/or local regulations may apply.